

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: San Juan 30-6 Unit 446	Facility Type: Gas Well

Surface Owner BLM	Mineral Owner BLM (NM-04139)	API No. 30-039-24590
--------------------------	-------------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter N	Section 35	Township 30N	Range 6W	Feet from the 1295	North/South Line South	Feet from the 1630	East/West Line West	County Rio Arriba
-------------------------	----------------------	------------------------	--------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude **36.7653** Longitude **107.43531**

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 5.57 bbls	Volume Recovered 2 bbls
Source of Release Wellhead	Date and Hour of Occurrence	Date and Hour of Discovery 11/5/12 at 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

**RCVD NOV 8 '12
OIL CONS. DIV.
DIST. 3**



Describe Cause of Problem and Remedial Action Taken.*

Well head packing failed and released approximately 5.57 bbls onto soil. Water truck was contacted to pull standing water and treatment will be implemented.

Describe Area Affected and Cleanup Action Taken.*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya		Approved by Environmental Specialist: 	
Title: Field Environmental Specialist		Approval Date: 11/27/2012 Expiration Date:	
E-mail Address: crystal.tafoya@conocophillips.com		Conditions of Approval:	
Date: 11/07/2012 Phone: (505) 326-9837		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

nJK 1233254051