				GY, MINERALS RCES DEPARTMENT CES DEPARTMENT OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm
			(sub 2 Ope	DENHEAD TEST REPORT Domit 1 copy to above address) Derator Richardson API #30-04/5-28336
Well Status(S	Shut-In o	r <u>Produc</u>	cing) Initial PS	Io.# Location: UnitSection 15 Township 28 NRange R8W SI: Tubing 16 Intermediate Casing 77 Bradenhead ATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
TestingBH	Bradenho	RESSUI ead Csg	RE INTERM Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min				Steady Flow
10 min				Surges
15 min 🗩		77		Down to Nothing
20 min				Nothing
25 min				Gas
30 min				Gas & Water
	↓ ₩_			Water
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR				
CLEAF	(FRESH_	SALTY	SULFURBLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD - INTERMEDIATE -				
REMARKS: XO PSI				
/6	0 - 01			
			<u> </u>	
By David Costalo Pamper				Witness
(Position)				
E-mail address _				
·				_

Ca

L