

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District Ill/3distric.htm

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

SEP 26 2012

Date of Test <u>09-11-12</u> Operat	tor Rich ardson API #30-0 45-31988
Property Name Fologa / 31-24 Well No. **	tor Rich ardson API #30-0 45-31988 NW4/5E4 * 3 Location: Unit Section 34 Township 28w Range Raw
Well Status(Shut-In or Producing) Initial PSI:	Tubing 7 Intermediate — Casing 10 Bradenhead 3
OPEN BRADENHEAD AND INTERMEDIATI	E TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min	Steady Flow
10 min	Surges
15 min 0 - 10	Down to Nothing
20 min	Nothing Nothing
25 min	Gas
30 min_	Gas & Water
	Water
If bradenhead flowed water, check all of the description	ons that apply below:
CLEAR FRESH SALTY	SULFURBLACK
5 MINUTE SHUT-IN PRESSURE BRADENH	EAD
REMARKS: NO PS,	
By Warie Costato	Witness
Pumper	
(Position) E-mail address	·
LEDON AURIESS	