



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD DEC 5 '12
OIL CONS. DIV.
DIST. 3

Date of Test 12/05/2012 Operator WPX API #30-045 - ²⁹¹⁴⁷~~29457~~

Property Name Rosa Unit Well No. 138 Location: Unit I Section 17 Township 31 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 560 Intermediate NA Casing 560 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	0		560		
10 min	0		560		
15 min	0		560		
20 min	0		560		
25 min	0		560		
30 min	0		560		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

Hurricane Rig #22 on well, running MIT w/ BHT, tubing open to casing.

By

Suzanne Smith
Project Consultant
(Position)

Witness

Jonathan D. Kelly

E-mail address _____