

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD **AZTEC NM 87410**

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

> Oil Cons. Div District III

BRADENHEAD TEST REPORT

AUG 1 4 2012

(suc	omit I copy to above address)
Date of Test 8-8-2012 Open	erator Black HIII5 API #30-039-27461
Property Name Jic 29-2-28 Well N	o. 2 Location: Unit Section 28 Township 29N Range 02 L
Well Status(Shut-In or Producing) Initial PS	II: Tubing 40 Intermediate Casing 31 Bradenhead 0
OPEN BRADENHEAD AND INTERMEDLE	ATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 0 30	Steady Flow
10 min 0 3/	Surges
15 min d 3/	Down to Nothing
20 min	Nothing Nothing
25 min_	Gas
30 min	Gas & Water
-	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
	NHEAD O INTERMEDIATE For test, no PSI on Braden head
By Judson Valder	Witness
By Judson Valder Lease operator (Position)	
E-mail address	
•	-

