	received						
	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			31 <b>201</b> 2	C Ex 5 Lease Social No	ORM APPROVED DMB No. 1004-0137 pires: October 31, 2014	
SUNDRY Do not use this abandoned well.	NOTICES AND REPO form for proposals to Use Form 3160-3 (Al	o drill or to	Ferenter	on Field Off and Manage an sals.	6) IPIndian, Allottee of	Tribe Name	
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No. NMNM-76319 (CA)		
Type of Well     Gas Well     Gas Well     Other					8. Well Name and No. Salazar G Com 23 #1		
2. Name of Operator Logos Operating, LLC					9. API Well No. 30-039-23314		
3a. Address 4001 North Buller Avenue, Building 7101 Farmington, NM 87401	3b. Phone No. 6 505-436-2627	include area	chude area code) 10. Field and Pool or Exploratory / Devils Fork Gallup (Associated				
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 790' FSL & 790' FWL Section 23, T25N, R06W, UL M				11. County or Parish, State Rio Arriba County, New Mexico			
12. CHI	ECK THE APPROPRIATE BO	X(ES) TO INDIO	CATE NATU	JRE OF NOTIC	E, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION TYPE OF ACT					ION		
Notice of Intent	Acidize	Deeper	re Treat		iction (Start/Resume) mation	Water Shut-Off Well Integrity	
	Casing Repair	=	onstruction id Abandon		mplete orarily Abandon	Other Pump Repair - Redelivery	
Final Abandonment Notice	Convert to Injection	Plug B			r Disposal	······	
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 10/19/12: MIRU. Start pulling rods out of hole and found rods to be parted. Pump 20 gallons of xylene down tubing. 10/22/12: Rig up hot oiler and hot oil casing with 35 BBLs heated to 240 degrees. Rig up Enviro fluid container. Start pulling rods with 12K over string weight. TOOH to parted rod at 196th jt (5/8" rod with body break). TIH to fish rods, stacked out fishing tool at 2600', unable to reach fish. TIH with paraffin knife and							
cut paraffin down to 2800'. TOOH with paraffin knife and prepare to strip out of hole. NUBOP. 10/23/12: PU tag joint and tag up at 6343'. TOOH with tubing and found jts 89-93 plugged with paraffin. TOOH to parted rod. Set tubing slips and latched onto parted rod. Unseated pump and TOOH with remaining rods and pump. TOOH with remaining tubing joints.							
10/24/12: PU tubing and BHA and TIH, setting EOT @ 6322' (KB), SN @ 6290' (KB). NDBOP. PU rods and pump and TIH, pump 300 gallons of xylene before seating pump. Seat pump and test tubing to 500 PSI. Long stroke pump with good pump action. RDMO.							
10/25/12: Returned well to production. Enterprise has installed a new gas meter.							
ALL FUTURE Sundry's include tubing weight & Grade							
Kristy Graham			Title Director of Administration and Engineering Support				
Signature that gal Date 10/30/2012							
THIS SPACE FOR FEDERAL OR STATE OFFICE U						MERTED FOR DEG	
Approved by			Fitle			Date NOV 1 9 2012	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or e that the applicant holds legal or equitable title to those rights in the subject lease which we entitle the applicant to conduct operations thereon.						ARMINGTON	
Title 18 U.S.C. Section 1001 and Title 4 fictitious or fraudulent statements or rep			son knowingl	y and willfully to	o make to any department	or agency of the United States any false,	
(Instructions on page 2)							