

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD JUL 17'12 OIL CONS. DIV. DIST. 3

Property Name Gallegos Fed 26-12-20 Well No.2 Location: Unit N Section 20 Township26N Range12W Well Status(Shut-In or Producing) Initial PSI: Tubing 78 Intermediate A Casing 1.1 Bradenhead OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH PRESSURE FLOW CHARACTERISTICS Testing Bradenhead INTERM BRADENHEAD INTERMEDIATE TIME 5 min
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg TIME 5 min I.I Steady Flow Surges 15 min One I.I Down to Nothing Nothing
PRESSURE
Testing Bradenhead INTERM BRADENHEAD INTERMEDIATE BH Int Csg Int Csg TIME 5 min
5 min 6 1.1 Steady Flow 10 min 6 1.1 Surges 15 min 1.1 Down to Nothing 20 min 1.1 Nothing
15 min
20 min
25 min — Gas
30 min Gas & Water Gas & Water
Water
If bradenhead flowed water, check all of the descriptions that apply below:
CLEAR FRESH SALTY SULFUR BLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE WA
By R.J. McKINNEY Witness
(Position) E-mail address bmckinney67@yahoo.com