

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD JUN 7'12 OIL CONS. DIV. DIST. 3

Date of Test June 7, 2012 Operator Vision ENERGY API #30-045-205580				
Property Name Navasol8 Well No. 9 Location: Unit F Section 18 Township 2911 Range 164				
Well Status(Shut-In or Producing) Initial PSI: Tubing 19 Intermediate MA Casing Vac Bradenhead 0				
OPEN BR	ADENHEAI	O AND INT	ERMEDIA	TE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
Testing	BH Int Csg Int Csg			FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min		og III	Csg	Steady Flow
10 min_				Surges
15 min				Down to Nothing
20 min				Nothing
25 min_				Gas
30 min				Gas & Water
				Water
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH SALTY SULFUR BLACK				
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE				
REMARKS:				
By fin The (Jim Hicks) Witness				
(Position)				
E-mail address hoginc 100/@qwest.net				