

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Crystal Tafoya	
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837	
Facility Name: San Juan 30-6 Unit 476	Facility Type: Gas Well	
Surface Owner BLM	Mineral Owner BLM (NM-04052)	API No. 30-039-24469

LOCATION OF RELEASE

Unit Letter A	Section 28	Township 30N	Range 6W	Feet from the 1060	North/South Line North	Feet from the 825	East/West Line East	County Rio Arriba
-------------------------	----------------------	------------------------	--------------------	------------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------------

Latitude **36.78792** Longitude **107.46164**

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 30 bbls	Volume Recovered 20 bbls
Source of Release Tank Bottom	Date and Hour of Occurrence 12/6/2012 at 12:00pm	Date and Hour of Discovery 12/6/12 at 1:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Sherri Landon (BLM) & Jonathan Kelly (OCD)	
By Whom? Crystal Tafoya	Date and Hour 12/6/2012 at 3:35pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCUD DEC 11 '12

If a Watercourse was Impacted, Describe Fully.*
N/A

**OIL CONS. DIV.
DIST. 3**



Describe Cause of Problem and Remedial Action Taken.*

A hole was discovered in the water tank bottom on the subject location which allowed 30bbls of produced water to be released. Approximately 20 bbls of produced water was recovered.

Describe Area Affected and Cleanup Action Taken.*

Soil sampling will be conducted to determine a path forward if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya		Approved by Environmental Specialist: 	
Title: Field Environmental Specialist		Approval Date: 12/20/2012 Expiration Date:	
E-mail Address: crystal.tafoya@conocophillips.com		Conditions of Approval:	
Date: 12/10/2012 Phone: (505) 326-9837		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

NJK 1235540941