

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised June 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Burlington Resources	Contact	Gregg Wurtz
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 320-2653
Facility Name	SAN JUAN 28-6 UNIT	130M	Facility Type Gas Well
Surface Owner	Fed	Mineral Owner	Fed
Lease No.		NMSF-079051	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	32	028N	006W	1700	South	820	East	San Juan

NATURE OF RELEASE

Type of Release	22 bbls oil and 3 bbls water	Volume of Release	25 BBLS.	Volume Recovered	0 BBLS.
Source of Release	Production Storage tank	Date and Hour of Occurrence	10/25/2004 7:00:00 AM	Date and Hour of Discovery	10/25/2004 4:00:00 PM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 0			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Corrosion hole on the side of the Production Tank, 6 inches from bottom. Corrosion could not be seen from outside of tank until hole developed. Soil excavated under and around tank and landfarmed on location. Work in progress.

Describe Area Affected and Cleanup Action Taken.*

Area around base of tank. Contained within the berm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gregg Wurtz</i>	OIL CONSERVATION DIVISION	
Printed Name: Gregg Wurtz	Approved by District Supervisor: <i>Denny Faint</i> for Frank Chavez	
Title: Environmental Representative	Approval Date: 11/5/04	Expiration Date:
E-mail Address: lhasely@br-inc. com or gwurtz@br-inc.com	Conditions of Approval: Land farm to be remediated.	Attached <input type="checkbox"/>
Date:	Phone: (505) 326-9841 or 9537	

* Attach Additional Sheets If Necessary

NDGIF 0431052758