<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Form C-141

Release Notification and Corrective Action OPERATOR Initial Report Final Report **Burlington Resources, a wholly** Name of Company Contact Gwen R. Frost owned subsidiary of ConocoPhillips Company 3401 E. 30th St., Farmington, NM 87402 Address Telephone No. 505-326-9866 San Juan 29-7 Unit #67M Facility Name Facility Type **Gas Well** API # 30-039-30440 Private Mineral Owner Federal SF-078399-424 Surface Owner Lease No. LOCATION OF RELEASE Feet from the North/South Line | Feet from the Unit Letter Section Township Range East/West Line County R07W 2000' K 23 **T29N** South 2210' West Rio Arriba 36.709550° N Longitude 107. 54139 ° W Latitude NATURE OF RELEASE Type of Release - Produced Water Volume of Release - 20 BBL Volume Recovered - 19.8 BBL **Produced Water** Source of Release: Tank overflow Date and Hour of Occurrence Date and Hour of Discovery 12/16/08 -11:00 a.m. Unknown If YES, To Whom? Was Immediate Notice Given? RCVD DEC 22 '08 ☐ Yes ☐ No ☒ Not Required OCD - Brandon Powell via email **Gwen Frost** By Whom? Date and Hour - 12/17/08 - 4:00 p.m. OH MAIC DILL If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? DIST. R ☐ Yes ⊠ No If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* On December 16, 2008 a COPC MSO discovered a water tank overflowing due to an increase in water production on the SJ 29-7 #67M. Upon discovery, the MSO shut in the well and called water hauler to come & recover the water. Approximately 20 BBL was spilled and all water was contained in the cribbing of the pit. All spilled fluids remained in the berm. Describe Area Affected and Cleanup Action Taken.* All of the spilled fluids remained on location. Approximately 19.8 BBL produced water was recovered. Soils will be monitored. To prevent reoccurrence, COPC will continue to monitor tank levels. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: For: CP Approved by District Supervisor: Gwen R. Frost Printed Name: Approval Date: 12/22/08 **Environmental Engineer Expiration Date:** Title:

Conditions of Approval:

* Attach Additional Sheets If Necessary

12/17/08

E-mail Address: gwendolynne.frost@conocophillips.com

Phone: 505-326-9549

Incident # 1 RMD 3929 334540

Attached