

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company <b>Burlington Resources Oil &amp; Gas Company</b>	Contact <b>Crystal Tafoya</b>	
Address <b>3401 East 30<sup>th</sup> St, Farmington, NM</b>	Telephone No. <b>(505) 326-9837</b>	
Facility Name: <b>San Juan 30-6 Unit 104M</b>	Facility Type: <b>Gas Well</b>	
Surface Owner <b>Federal</b>	Mineral Owner <b>Federal (NM-02151)</b>	API No. <b>30-039-30817</b>

### LOCATION OF RELEASE

Unit Letter <b>A</b>	Section <b>28</b>	Township <b>30N</b>	Range <b>7W</b>	Feet from the <b>594</b>	North/South Line <b>North</b>	Feet from the <b>677</b>	East/West Line <b>East</b>	County <b>Rio Arriba</b>
-------------------------	----------------------	------------------------	--------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------------

Latitude **36.789256** Longitude **107.569046**

### NATURE OF RELEASE

Type of Release <b>Condensate</b>	Volume of Release <b>8.02bbls</b>	Volume Recovered <b>0 bbls</b>
Source of Release <b>Production Tank</b>	Date and Hour of Occurrence	Date and Hour of Discovery <b>1/2/2013 at 1:30 pm</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	<b>RCVD JAN 14 '13</b>
By Whom?	Date and Hour	<b>OIL CONS. DIV.</b>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	<b>DIST. 3</b>

If a Watercourse was Impacted, Describe Fully.\*  
**N/A**



Describe Cause of Problem and Remedial Action Taken.\*

**A hole in the bottom of the oil production tank was believed to be the cause of the release of 8.02bbls. However after investigation and tank inspection it was discovered a hole is not in the production tank and there is no visibly impacted soil. Soil sampling was conducted and field results are attached. After investigating it is believe that the missing 8.02bbls is a result of theft.**

Describe Area Affected and Cleanup Action Taken.\*

**Soil sampling was conducted and attached are the field results. No further remedial action will be taken on this project.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Crystal Tafoya</b>	Approved by Environmental Specialist: 	
Title: <b>Field Environmental Specialist</b>	Approval Date: <b>1/30/2013</b>	Expiration Date:
E-mail Address: <b>crystal.tafoya@conocophillips.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>1/9/2013</b> Phone: <b>(505) 326-9837</b>		

\* Attach Additional Sheets If Necessary

**JK1303028373**

**Tafoya, Crystal**

---

**From:** Deborah Watson [dywatson@animasenvironmental.com]**Sent:** Wednesday, January 09, 2013 1:32 PM**To:** Tafoya, Crystal**Subject:** [EXTERNAL]San Juan 30-6 Unit 104M

Samples were collected along the gravel pad and within the containment berm.

Sample ID	Sample Location	OVN (ppm)	TPH (mg/kg)
SB-1	NE	0.8	51.4
SB-2	NW	0.5	<40.0
SB-3	SE	1.3	<40.0
SB-4	SW	1.9	<40.0
SB-5	W	1.6	<40.0
SB-6	W	2.9	<40.0
SB-7	N	1.7	<40.0
SB-8	E	1.4	85.2
SB-9	S	1.4	85.2

Please call with any questions.

Debbie

**Deborah Watson**

Project Manager

Animas Environmental Services, LLC

624 E. Comanche

Farmington, NM 87401

office: (505) 564-2281

cell: (505) 486-4071

fax: (505) 324-2022

[dywatson@animasenvironmental.com](mailto:dywatson@animasenvironmental.com)

WOMAN-OWNED SMALL BUSINESS

[www.animasenvironmental.com](http://www.animasenvironmental.com)

*NOTICE: This e-mail (and any attachments) may contain PRIVILEGED OR CONFIDENTIAL information and is intended only for the use of the specific individual(s) to whom it is addressed. It may contain information that is privileged and confidential under state and federal law. This information may be used or disclosed only in accordance with law, and you may be subject to penalties under law for improper use or further disclosure of the information in this e-mail and its attachments. If you have received this e-mail in error, please immediately notify the person named above by reply e-mail, and then delete the original e-mail. Thank you.*