

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: San Juan 31-6 Unit 206	Facility Type: Gas Well

Surface Owner BLM	Mineral Owner BLM (SF-079012)	API No. 30-039-24445
--------------------------	--------------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter N	Section 4	Township 30N	Range 6W	Feet from the 925	North/South Line South	Feet from the 1450	East/West Line West	County Rio Arriba
-------------------------	---------------------	------------------------	--------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude 36.83674 Longitude 107.47171

NATURE OF RELEASE



Type of Release Produced Water	Volume of Release 75 bbls	Volume Recovered 55 bbls
Source of Release Transfer Pump	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 12/13/12 at 11:50am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell (OCD) & Sherri Landon (BLM)	
By Whom? Crystal Tafoya	Date and Hour 12/13/2012 at 2:43pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. RCVD DEC 19 '12 OIL CONS. DIV.	

If a Watercourse was Impacted, Describe Fully.* N/A	DIST. 3
---	----------------

Describe Cause of Problem and Remedial Action Taken.*
Transfer Pump froze and came loose from the connection fitting released 75bbls. A water truck was called to location and 55bbls was recovered. 20 bbls was contained within the berm and remained on location. The well has been shut-in until the transfer pump can be repaired.

Describe Area Affected and Cleanup Action Taken.*
Soil sampling will be conducted by a third party to determine a path forward if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya		Approved by Environmental Specialist: 	
Title: Field Environmental Specialist		Approval Date: 2/11/2013	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/18/2012 Phone: (505) 326-9837			

* Attach Additional Sheets If Necessary

nJK 1304238849