

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: San Juan 32-7 Unit 222	Facility Type: Gas Well

Surface Owner Federal	Mineral Owner Federal (SF-078460)	API No. 30-045-28735
------------------------------	--	-----------------------------

LOCATION OF RELEASE

Unit Letter H	Section 20	Township 32N	Range 7W	Feet from the 2249	North/South Line North	Feet from the 876	East/West Line East	County San Juan
-------------------------	----------------------	------------------------	--------------------	------------------------------	----------------------------------	-----------------------------	-------------------------------	---------------------------

Latitude **36.96663** Longitude **107.5838**

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 18 bbls	Volume Recovered
Source of Release Produced Water Tank	Date and Hour of Occurrence	Date and Hour of Discovery 1/9/2013 at 2:00pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	RCVD JAN 15 '13
By Whom?	Date and Hour	OIL CONS. DIV.
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	DIST. 3

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

4" butterfly valve on produced water tank froze and broke releasing 18bbls of produced water. Well was shut in, water truck called to pull standing fluid.

Describe Area Affected and Cleanup Action Taken.*

Soil sampling will be conducted by a third party to determine a path forward if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya		Approved by Environmental Specialist: 	
Title: Field Environmental Specialist		Approval Date: 2/1/2013	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/11/2013 Phone: (505) 326-9837			

* Attach Additional Sheets If Necessary

nJK 13042 38652