

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company <b>Burlington Resources Oil &amp; Gas Company</b>	Contact <b>Crystal Tafoya</b>
Address <b>3401 East 30<sup>th</sup> St, Farmington, NM</b>	Telephone No. <b>(505) 326-9837</b>
Facility Name: <b>Nye SRC 15N</b>	Facility Type: <b>Gas Well</b>

Surface Owner <b>Federal</b>	Mineral Owner <b>Federal (SF-078198)</b>	API No. <b>30-045-34143</b>
------------------------------	--	-----------------------------

**LOCATION OF RELEASE**

Unit Letter <b>B</b>	Section <b>25</b>	Township <b>30N</b>	Range <b>11W</b>	Feet from the <b>660</b>	North/South Line <b>North</b>	Feet from the <b>1885</b>	East/West Line <b>East</b>	County <b>San Juan</b>
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

Latitude **36.7881728** Longitude **107.93972**

**NATURE OF RELEASE**

Type of Release <b>Condensate</b>	Volume of Release <b>22.5 bbls</b>	Volume Recovered <b>0 bbls</b>
Source of Release <b>Condensate Tank</b>	Date and Hour of Occurrence	Date and Hour of Discovery <b>1/7/2013 at 1:30 pm</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <b>RCVD JAN 14 '13</b>	
By Whom?	Date and Hour <b>OIL CONS. DIV.</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>DIST. 3</b>	

If a Watercourse was Impacted, Describe Fully.\*  
**N/A**



Describe Cause of Problem and Remedial Action Taken.\*

**Condensate tank was vandalized with a bullet hole at a height of 2' 11" from the bottom of the tank, releasing approximately 22.5 bbls. Well was shut in and isolated oil side dump controller.**

Describe Area Affected and Cleanup Action Taken.\*

**Visually affected area is approximately 30' X 30'. Soil sampling will be conducted by a third party to determine a path forward if necessary.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Crystal Tafoya</b>		Approved by Environmental Specialist: 	
Title: <b>Field Environmental Specialist</b>		Approval Date: <u><b>2/1/2014</b></u> Expiration Date:	
E-mail Address: <b>crystal.tafoya@conocophillips.com</b>		Conditions of Approval:	
Date: <b>1/8/2013</b> Phone: <b>(505) 326-9837</b>		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

**NJK1304237114**