Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SHAPPY NOTICES AND PEPOPTS ON WELLS

5. Lease Serial No. NMSF078828A

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					14101010102011		
					6. If Indian, Allottee or Tribe Name EASTERN NAVAJO		
SUBMIT IN TRI	erse side.		7. If Unit or CA/Agreement, Name and/or No. 892000844F				
Type of Well					8. Well Name and No. GALLEGOS CANYON UNIT 184		
Name of Operator     BP AMERICA PRODUCTION	IN '		9. API Well No. 30-045-07207-00-S1				
3a. Address 200 ENERGY COURT FARMINGTON, NM 87401  3b. Phone No Ph: 281-36			. (include area code 6-7148	:)	10. Field and Pool, or Exploratory BASIN DAKOTA		
4. Location of Well (Footage, Sec., 7			11. County or Parish, and State				
Sec 28 T28N R12W NENE 11 36.637300 N Lat, 108.111620			SAN JUAN COUNTY, NM				
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF	NOTICE, RE	PORT, OR OTHER	DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
□ Notice of Intent	☐ Acidize	☐ Dee		☐ Production	on (Start/Resume)	☐ Water Shut-Off	
Subsequent Report     ■     Subsequent Report     Subse	☐ Alter Casing	☐ Fracture Treat		Reclama		☐ Well Integrity	
	Casing Repair	_	Construction	☐ Recompl		☐ Other	
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection			☐ I empora	rily Abandon		
testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  1/21/2013 MIRU RIG, Perform inspections, R/U flowback equipment, vent csg and tbg down, raise and secure derrick, R/U 2" Surface Lines and Rig Pump, secured well and location  1/25/13 MIRU Cement Equipment, pressure test pump lines, Squeeze Dakota Perfs 6090'-4842' w/147 sacks G-Class 15.80 ppg cement. Displaced 6.4 bbls of cement w/water during Dakota perf squeeze, pressured up to 1400 psi and lost rate, stung out of retainer and balanced 16 bbls of G-class cement on top of retainer.  1/28/13 TIH TAG TOC @ 4842', Pressure Tested Csg-Passed, Set 2 Stage Cement Plugs from 3100'-2050' w/16.7 bbls pumped and displaced G-class 15.80 ppg cement, MIRU Pressure Test Cement Pump-Passed, and Set Cement Plug from 2050'-1000' w/16.7 bbls pumped and displaced G-class 15.80 ppg cement. Total 164 sacks used for cement plugs.							
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #198701 verified by the BLM Well Information System  For BP AMERICA PRODUCTION CO, sent to the Farmington  Committed to AFMSS for processing by STEVE MASON on 02/13/2013 (12JXL0130SE)							
Name (Printed/Typed) TOYA COLVIN			Title REGUI	_ATORY ANA	LYST	<u>.</u>	
Signature (Electronic Submission)			Date 02/12/2013				
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE US	E		
_Approved_By_ACCEPTED				N MASON EUM ENGINEER Date 02/13/2013			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Farmington				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a c statements or representations as t	rime for any pe to any matter w	rson knowingly and thin its jurisdiction	d willfully to ma	ke to any department or a	gency of the United	

## Additional data for EC transaction #198701 that would not fit on the form

## 32. Additional remarks, continued

1/29/13-1/30/13 Vented Braden Head for 2 hrs, SHut in Braden Head and monitored pressures 6 hrs \* reaching 20 psi. TiH and TAG TOC @ 1170', TIH Standing Back 19 STDS, MIRU E-Line, RIH w/ E-line and TAG TOC @ 1146', Performed CBL, notified Engineer of results, N/U Frac Valve on top of BOP, Shut in Well.

1/31/13 MIRU and pressure test E-Line unit, RIH and Perforate 735'-745'. POOH and attempt to inject w/water.

2/1/13 MIRU TIH w/2.375" TBG to 1170', Tagged TOC. Set Cement Plug from 1170'-450' w/57 sacks G-Class 15.80 ppg cement. Perform Hesitation Squeeze, RDMO CMT.

2/5/13-2/7/13 MIRU and pressure test E-Line, Perforate from 328'-332' and 228'-234' for circulation and cement squeeze. Attempt to circulate pressuring up to 800 psi, Bled off csg, shut in well.

2/8/13 MIRU, checked Shut In Pressure, TiH to 420', MIRU and Pressure Test Cement, Pumped 6 bbls G-class Cement down TBG, TOOH Laying Down, Landed Hanger w/PUP and TIW, Squeeze perfs @ 420'-1' w/34 sacks G-class 15.80 ppg cement. RDMO Cement, Shut In Well.

2/11/13 MIRU Cold Cut Wellhead off, Verified Cement to Surface, Released TBG Float and cleaned BOP. This well in Crop Circle NAPI, will install dry hole marker 6' below surface and leave open per BLM requirments.

------