

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP America Production Company	Contact: Courtney Cochran
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457
Facility Name: Riddle H5	Facility Type: Natural Gas Well

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3004513003
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter D	Section 21	Township 30N	Range 09W	Feet from the 825	North/South Line North	Feet from the 890	East/West Line West	County San Juan
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	-----------------

Latitude 36.80203 Longitude 107.79141

NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 221 MCF	Volume Recovered: none
Source of Release: damaged piping	Date and Hour of Occurrence: 2/1/2013 11:50 am.- noon	Date and Hour of Discovery: 2/1/2013
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? RCVD FEB 11 '13	
By Whom?	Date and Hour	OIL CONS. DIV.
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. DIST. 3	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Optimizer contacted and informed that private citizen had backed into an above ground valve on location. Field technician arrived shortly thereafter and found piping bent and blowing produced water and natural gas. Well was immediately shut-in.

Describe Area Affected and Cleanup Action Taken.*

Natural gas dissipated to atmosphere so no clean-up action possible. Produced water volume small and raked into soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by Environmental Specialist: 	
Title: Field Environmental Advisor	Approval Date: 2/27/2013	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/8/2013	Phone: 505-326-9457	

* Attach Additional Sheets If Necessary

15K1305849363