

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: McGrath 4	Facility Type: SWD

Surface Owner Private	Mineral Owner Federal (SF-077922)	API No. 3004525923
------------------------------	--	---------------------------

LOCATION OF RELEASE

Unit Letter B	Section 34	Township 30N	Range 12W	Feet from the 800	North/South Line North	Feet from the 1730	East/West Line East	County San Juan
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

Latitude 36.77417 Longitude 108.08192

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 5 bbls	Volume Recovered 5 bbls
Source of Release Third Party - Water Truck	Date and Hour of Occurrence 11/14/2012 at 12:15pm	Date and Hour of Discovery 11/14/12 at 12:17pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? RCVD NOV 21 '12	
By Whom?	Date and Hour OIL CONS. DIV.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. DIST. 3	

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

Third party water truck driver was offloading when the screen became plugged. Driver disconnected the hose without shutting off discharge valve causing 5 bbls of Produced Water to be released.

Describe Area Affected and Cleanup Action Taken.*

The water was removed by the truck driver and micro blaze was raked into the soil. Sampling will not take place and the affected area will continue to be monitored. Testing and remediation will take place at closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya		Approved by Environmental Specialist: 	
Title: Field Environmental Specialist		Approval Date: 3/07/2013	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/20/2012 Phone: (505) 326-9837			

* Attach Additional Sheets If Necessary

NJK1306653.503