

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-34280

OPERATOR		<input type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company Noble Energy, Inc.	Contact Jacob Evans		
Address 5802 U.S. Hwy. 64, Farmington, NM 87401	Telephone No. 303.228.4158		
Facility Name Shootist 19-16	Facility Type Tank Battery		
Surface Owner Federal (BLM)	Mineral Owner Federal (BLM)	Lease No. NMSF 078244	

LOCATION OF RELEASE

Unit Letter P	Section 19	Township 31N	Range 12W	Feet from the 660	North/South Line FSL	Feet from the 660	East/West Line FEL	County San Juan
-------------------------	----------------------	------------------------	---------------------	-----------------------------	--------------------------------	-----------------------------	------------------------------	---------------------------

Latitude **36.5246 N** Longitude **108.0752 W**

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 10 BBLS	Volume Recovered 10 BBLS
Source of Release Tank Overrun	Date and Hour of Occurrence 1/7/2013 Unknown	Date and Hour of Discovery 1/8/2013 12:00 Noon
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? NA	
By Whom? NA	RCVD JAN 18 '13	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Date and Hour NA OIL CONS. DIV.	
If a Watercourse was Impacted, Describe Fully.* N/A	If YES, Volume Impacting the Watercourse. NA DIST. 3	
Describe Cause of Problem and Remedial Action Taken.* After a pump was down on the well, unforeseen water production overran the tank. Approximately 10 BBLS of produced water was released into the lined secondary containment.		
Describe Area Affected and Cleanup Action Taken.* Vac truck removed produced water and excess stormwater from the secondary containment. Produced water was hauled to an injection facility for disposal.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jacob Evans</i>		OIL CONSERVATION DIVISION	
Printed Name: Jacob Evans		Approved by District Supervisor: <i>Joan Kelly</i>	
Title: Sr. Environmental Specialist		Approval Date: 3/7/2013 Expiration Date: 3/7/2013	
E-mail Address: jevans@nobleenergyinc.com		Conditions of Approval:	
Date: _____ Phone: 720-587-2026		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

nJR 130664 7575