Form 3160-5

UNITED STATES

FORM APPROVED

(August 2007)	RURFALLOF LAND MANAGEMENT			OMB No. 1004-0137 Expires: July 31, 2010 5. Lease Serial No.	
Do not use	DRY NOTICES AND REPO this form for proposals to well. Use Form 3160-3 (A	DRTS ON WELESrmin o drill or totre-entercái	gton F i.and	SF ទែទ្ធាំស្នាក់ពីផ្តែកុំស្នែllottee or Tribe N	F-078951 fame
SUBMIT IN TRIPLICATE - Other instructions on page 2.				7. If Unit of CA/Agreement, Na	ame and/or No.
1. Type of Well				San Juan 29-7 Unit	
Oil Well X Gas Well Other				8. Well Name and No. San Juan 29-7 Unit 79	
2. Name of Operator				9. API Well No.	
Burlington Resources Oil & Gas Company LP				30-039-07683	
3a. Address PO Box 4289, Farmingtor	3b. Phone No. (include area coo (505) 326-9700	-	10. Field and Pool or Exploratory Area Blanco Mesa Verde		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) Surface UNIT M (SWSW), 990' FSL & 990' FWL, Sec. 5, T29N, R7W				11. Country or Parish, State Rio Arriba ,	, New Mexico
12. CHECK T	HE APPROPRIATE BOX(ES)	TO INDICATE NATURE	OF NOT	FICE, REPORT OR OTHE	ER DATA
TYPE OF SUBMISSION TYPE OF ACTION					
Notice of Intent X Subsequent Report Final Abandonment Notice	Acidize Alter Casing X Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	R R	roduction (Start/Resume) eclamation ecomplete emporarily Abandon //ater Disposal	Water Shut-Off Well Integrity X Other Casing Repair
Attach the bond under which the we following completion of the involve	nally or recomplete horizontally, give ork will be performed or provide the E ed operations. If the operation results Abandonment Notices must be filed o final inspection.)	subsurface locations and measur and No. on file with BLM/BIA. in a multiple completion or recor	ed and tru Required inpletion	ue vertical depths of all pertinen d subsequent reports must be file in a new interval, a Form 3160-4 mation, have been completed an	t markers and zones. ed within 30 days 4 must be filed once d the operator has CVD FEB 25 *13
. LEAGE GET AT TAGIT				0	IL CONS. DIV. DIST. 3

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) DENISE JOURNEY Title REGULATORY TECHNICIAN 2/12/2013 ourner Signature Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify PAFARINGTON FIELD OFFICE Office that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

SAN JUAN 29-7 UNIT 79 30-039-07683 Burlington Resources Blanco Mesaverde

Page 2 – Tubing Repair Subsequent Sundry

12/26/12 – MIRU AWS 753. ND WH. NU BOPE. PT BOPE. Test OK. TOOH w/ 2 3/8" tubing. CO to PBTD @ 5,230'.

1/2/13 – Attempt to set Packer, would not hold. Tlh, ream through 4 ½" casing patch. TlH w/ 4 ½" RBP, set @ 3,020' and 4 ½" packer set @ 61', 31', & 12' – test failed – had gas flow, test @ 3,202' – no gas flow.

1/3/13 - ND Tubing head, install new tubing head. NU BOPE. PT BOPE. Test OK.

1/5/13 – TIH w/ 4 1/2" packer, set @ 2,900', isolate casing leak between 1,791' & 1,822'.

1/7/13 – TOOH w/ 4 ½" packer. RU WL, run GR CCL/CASING INSPECTION LOG from 3,015' to surface. Log shows bad casing @ 1,806' & 1,812'.

1/8/13 – Notified Agencies, Troy Salyers (BLM) and Brandon Powell (NMOCD) bad casing @ 1,806' & 1,812'. Plan forward is to remove 4 ½" casing below the casing patch, run CBL to verify cement tops, re-run 4 ½" casing and cement to surface. Verbal approval received to proceed with procedure sent to Troy Salyers (BLM) and Brandon Powell (NMOCD).

1/10/13 – RU WL. Free Point 4 ½" casing. TIH w/ Chemical cutter, chemically cut 4 ½" casing @ 2,892'. TOOH w/ cutter. RD WL. TOOH w/ 53 jts., cut off 4 ½" casing. RU WL Run CBL from 2,892' to surface-good cement bond.

1/14/13 – Notified Agencies Steve Mason (BLM) and Brandon Powell (NMOCD) – CBL run on 1/10/13 shows good cement from 7" setting depth of 2,885' to surface. Plan forward is to re-run the 4 $\frac{1}{2}$ " casing and cement to surface. Verbal approval received from Steve Mason (BLM) and Brandon Powell (NMOCD).

1/17/13 - TIH w/ 71 its., 4 ½", 10.5#, J-55 casing set @ 2.896' (new setting depth).

1/18/13 – RU WL. TIH w/ squeeze gun, shoot 3, .40" diam. Perfs @ 2,910'. TOOH w/ gun. RD WL. TIH w/ 4 ½" packer, set @ 2,689' – PT casing & packer from 2,689' to surface – good test. 1/19/13 – RU to cement. Pump 360 sx, Type III cement through perfs. @ 2,910', circ. through bradenhead @ surface. Displace w/ 13.5 bbls. FW, Circ 15 bbls. good cmt. to surface. RD Cmt., WOC.

1/21/13 - TOOH w/ packer.

1/22/13 - TIH, tag cement @ 2,850' & DO to 2,996'. Circ. clean. RU Wilson. PT 4 ½" casing – failed – witnessed by John & NMOCD.

1/23/13 – Perform MIT test on 4 ½" casing, witnessed by Paul Wilke (NMOCD) – test passed. **1/24/13** – TIH w/ 167 jts., 2 3/8", 4.7#, J-55 tubing, set @ 5,183' w/ FN @ 5,181'. ND WH. NU BOPE. PT tubing 500#/30 min. Test OK. RD RR @ 18:00 hrs on 1/24/13.