

(Position)

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1090 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8178 FAX: (505) 334-8170
http://emrard.state.nm.us/ocd/District III/3distric.htm

OIL CONS. DIV DIST. 3
MAR 2 5 2013

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test	3-20-13	Operator	ENERDYNE LLC	_API #30-0_	31-20860
Property Name_	CHACO WASH MY	Well No. 029	Location: Unit_G_S	ection_28_To	ownship 20N Range 9W
Well Status(Shu	ut-In or Producing	g) Tubing <u>5/8"</u> Ir	ntermediate NA Casi	ng 4.5" Brai	ndenhead NA
OPEN BRADI	ENHEAD AND IN	TERMEDIATE TO	ATMOSPHERE INDIV	/IDUALLY FC	OR 15 MINUTES EACH
PRESSURES:			BRADENHEAD		
INTERMEDIATE TIME 1	NTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes_			Down to Nothing	g	
20 minutes			Nothing		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY SULFUR BLACK					
	r-in bradenhi	EAD	INTERMEDIATE		
REMARKS: SHALL	LOW MENEFEE W	ELL THAT PRODU	CES FRESH WATER V	VITH OIL- PRO	DUCTION CASING ONLY- NO
SU	IRFACE CASING (OR BRADENHEAD.			
By DON L. HANOSH		Witness			
MANAGING) MEMBEK				