



**OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnr.d.state.nm.us/ocd/District III/3ddistrict.htm](http://emnr.d.state.nm.us/ocd/District%20III/3ddistrict.htm)**

OIL CONS. DIV DIST. 3

MAR 25 2013

# BRADENHEAD TEST REPORT

**(submit 2 copies to above address)**

Date of Test      3-20-13      Operator      ENERDYNE LLC      API #30-0      31-20902

Property Name **CHACO WASH MV** Well No. **033** Location: Unit H Section **28** Township **20N** Range **9W**

Well Status(Shut-In or Producing)	Tubing 5/8" Intermediate NA	Casing 4.5" Brandenhead NA
-----------------------------------	-----------------------------	----------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**PRESSURES:**

## BRADENHEAD

INTERMEDIATE  
TIME

**INTERMEDIATE**

## CASING

FLOWED

FLOWED

5 minutes

## Steady Flow

**10 minutes**

## Surges

15 minutes

## Down to Nothing

20 minutes

**Nothing**

25 minutes

## Gas

30 minutes

## Gas & Water

## Water

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR                  FRESH                  SALTY                  SULFUR                  BLACK

## 5 MINUTE SHUT-IN      BRADENHEAD      INTERMEDIATE

REMARKS:

**SHALLOW MENEFEE WELL THAT PRODUCES FRESH WATER WITH OIL- PRODUCTION CASING ONLY- NO**

**SURFACE CASING OR BRADENHEAD.**

By **DON L. HANOSH**

**Witness** \_\_\_\_\_

## MANAGING MEMBER

(Position)