

By DON L. HANOSH

(Position)

MANAGING MEMBER

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emrrd.state.nm.us/ocd/District II/Jdistric.htm

OIL CONS. DIV DIST. 3

## BRADENHEAD TEST REPORT (submit 2 copies to above address)

MAR 2 5 2013

3-20-13 Operator ENERDYNE LLC API #30-0 31-20964 Date of Test Property Name CHACO WASH MV Well No. 202 Location: Unit M Section 22 Township 20N Range 9W Well Status(Shut-In or Producing) Tubing 1" Intermediate NA Casing 4.5" Brandenhead NA OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH PRESSURES: **BRADENHEAD INTERMEDIATE** TIME INTERMEDIATE CASING FLOWED FLOWED Steady Flow 5 minutes 10 minutes Surges Down to Nothing 15 minutes Nothing 20 minutes 25 minutes Gas & Water 30 minutes Water If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK 5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE REMARKS SHALLOW MENEFEE WELL THAT PRODUCES FRESH WATER WITH OIL- PRODUCTION CASING ONLY- NO SURFACE CASING OR BRADENHEAD.

Witness