

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-5178 FAX: (505) 334-5170
http://emprd.state.nm.us/ocd/District III/3distric.htm

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

MAR 19 2013

(submit 2 copies to above address)

Date of Test	3-17-13	Operator	ENERDYNE LI	LC API #30-0 31-	-05395
Property Name RED	MOUNTAIN N	Well No. 02	Location: Unit	O Section 20 Towns	hip 20N Range 9W
Well Status(Shut-In	or Producing	Tubing 1.25	"Intermediate_NA_	Casing 4.5" Branden	head NA
OPEN BRADENH	EAD AND IN	ΓERMEDIATE Τ	O ATMOSPHERE II	NDIVIDUALLY FOR 15	MINUTES EACH
PRESSURES:			BRADENHEAD		
INTERMEDIATE TIME <u>INTE</u>	RMEDIATE	CASING	·	FLOWED	FLOWED
5 minutes			Steady Flor	w	
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			Nothing		·
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		
lf bradenhead flowed w	vater, check all	of the description:	s that apply below:		
CLEAR	FRESH	SALTY	SULFURI	BLACK	
MINUTE SHUT-IN BRADENHEAD		AD	INTERMEDIATE		
REMARKS: SHALLOW	MENEFEE W	ELL THAT PROF	DUCES ERESH WAT	FR WITH OU - PRODUC	CTION CASING ONLY- N
		R BRADENHEA		EK WIIII OIE- PRODUC	TION CASING ONL 1- N
By DON L. HANOSH		Witne	ss		
MANAGING ME	MBER				