

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 67410
(505) 334-6178 FAX: (505) 334-6170
http://emmrd.state.nm.us/ocd/District III/3distric.htm

OIL CONS. DIV DIST. 3

MAR 1 9 2013

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test	3-17-13	Operator	ENERDYNE LLC	_API #30-0_	31-20565
Property Name RED MOUNTAIN MV Well No. 047 Location: Unit O Section 20 Township 20N Range 9W					
Well Status(Shut-In or Producing) Tubing 1.25"Intermediate NA Casing 4.5" Brandenhead NA					
OPEN BRADE	NHEAD AND I	NTERMEDIATE TO	ATMOSPHERE INDIV	/IDUALLY FO	R 15 MINUTES EACH
PRESSURES:			BRADENHEAD		
INTERMEDIATE TIME IN	TERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		· · · · · · · · · · · · · · · · · · ·	Steady Flow	· · · · · · · · · · · · · · · · · · ·	
10 minutes			Surges		
15 minutes		Down to Nothing			<u>}</u>
20 minutes					
25 minutes					
30 minutes			Gas & Water		
			Water		
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY SULFUR BLACK					
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE					
REMARKS: SHALL	OW MENEFEE V	VELL THAT PRODU	CES FRESH WATER V	VITH OIL- PRO	DUCTION CASING ONLY- NO
SUF	RFACE CASING	OR BRADENHEAD.			
				W 	
By DON L. HANOSH Witness					
MANAGING (Position)	MEMBER				