



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://amnr.dnr.state.nm.us/ocd/District103/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV DIST. 3

APR 11 2013

Date of Test 4-3-13 Operator Cherxon midcont API #30-0 39-07052

Property Name Rincon Well No. 177 Location: Unit 4 Section 13 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 34 Intermediate X Casing 48 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		48		
10 min	0		48		
15 min	0		48		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE X

REMARKS:

By Randy calcoTE
calder services
(Position)

Witness _____

E-mail address Randy.c@calderservices.com

4-5-13