



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emard.state.nm.us/ocd/District1102/district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

APR 04 2013

Date of Test 3-28-13 Operator Chevron mid cont API #30-039-06831

Property Name Rincon Well No. 130 Location: Unit A Section 32 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 41 Intermediate 4 Casing 142 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	0	4	142	Light 139 psi	142
10 min	0	4	142	0	142
15 min	0	4	142	0	142
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Intermediate Blew down to Light Blow in 30 sec
Then Light Blow for 5 min then dead

By Randy calder
calder services
(Position)

Witness _____

E-mail address Randy.c@calderservices.com

4-2-13