

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company ConocoPhillips Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: San Juan 31-6 Unit 46F	Facility Type: Gas Well

Surface Owner BLM	Mineral Owner State (E-346-47)	API No. 30-039-29900
--------------------------	---------------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter J	Section 32	Township 31N	Range 6W	Feet from the 2200	North/South Line South	Feet from the 1440	East/West Line East	County Rio Arriba
-------------------------	----------------------	------------------------	--------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude **36.85484** Longitude **107.48215**

NATURE OF RELEASE



Type of Release Natural Gas	Volume of Release 66 mcf	Volume Recovered None
Source of Release Separator - Rupture Disc	Date and Hour of Occurrence 4/7/2013 at 11:45pm	Date and Hour of Discovery 4/8/2013 at 8:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* N/A	RCVD APR 15 '13 OIL CONS. DIV. DIST. 3
---	---

Describe Cause of Problem and Remedial Action Taken.*
MSO found rupture disc on the separator had popped and engineer calculated natural gas release of 66mcf. The well was immediately shut-in and the rupture disc replaced.

Describe Area Affected and Cleanup Action Taken.*
No further action will be taken on this release.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya		Approved by Environmental Specialist: 	
Title: Field Environmental Specialist		Approval Date: 5/21/2013	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/11/2013 Phone: (505) 326-9837			

* Attach Additional Sheets If Necessary

NSK 1314148843