

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP America Production Company	Contact: Courtney Cochran
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457
Facility Name: Florance I 38A	Facility Type: Natural Gas Well

Surface Owner: Federal	Mineral Owner: Federal	API No.: 300452186000
------------------------	------------------------	-----------------------

LOCATION OF RELEASE

Unit Letter F	Section 14	Township 30N	Range 08W	Feet from the 1622	North/South Line North	Feet from the 2010	East/West Line West	County: San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 36.81294 Longitude 107.64571

NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 145 MCF	Volume Recovered: none
Source of Release: piping	Date and Hour of Occurrence: 4/15/13	Date and Hour of Discovery: 4/15/13
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



RCVD APR 18 '13
OIL CONS. DIV.
DIST. 3

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Field technician found gas blowing around the 3 ball manifold by the separator where the discharge line from compressor ties into it. Well is shut-in.

Describe Area Affected and Cleanup Action Taken.*
Natural gas dissipated to atmosphere, so no clean-up action possible.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by Environmental Specialist: 	
Title: Field Environmental Advisor	Approval Date: 5/21/2013	Expiration Date:
E-mail Address: Courtney Cochran	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/16/2013	Phone: 505-326-9457	

* Attach Additional Sheets If Necessary

n57K1314140650