



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

RCVD JUN 6 '13
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-JUNE-2013 Operator CONOCO API #30-0 39- 22812
Property Name SAN JUAN 27-9 Well No. 139 Location: Unit 1 Section 9 Township 27 Range 4
Well Status(Shut-In or Producing) Initial PSI: Tubing 160 Intermediate N/A Casing 164 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	<u>1</u>	<u>N/A</u>	<u>164</u>		
10 min	<u>1</u>	<u>N/A</u>	<u>164</u>		
15 min	<u>1</u>	<u>N/A</u>	<u>164</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>X</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT.

By Cory Schmitt

Witness John D. [Signature]

(Position)

E-mail address _____