# RECEIVED

ומוזמ	UNITED STATES PARTMENT OF THE INT EAU OF LAND MANAC	EMENT	08 2013	C Ex 5 Lease Serial No.	ORM APPROVED OMB No. 1004-0137 pires: October 31, 2014
Do not use tins i	OTICES AND REPORT form for proposals to c Use Form 3160-3 (APD	ırın or to re-enter a	1	MMSF- 078807A 6-1-FIndian, Allottee or	Tribe Name
	TIN TRIPLICATE - Other ins	tructions on page 2.		7. If Unit of CA/Agree	ment, Name and/or No.
1. Type of Well  Oil Well  Gas W	ell			8. Well Name and No. Federal Com #2R	
Name of Operator     McElvain Energy, Inc.	- "			9. API Well No. 30-045-23512	
3a. Address       3b. Phone No. (include area code)         1050 17th St, Suite 2500, Denver, CO 80265       303-893-0933				10. Field and Pool or Exploratory Area Basin Dakota	
4. Location of Well (Footage, Sec., T., 1085' FSL & 285' FWL SWSW SEC 12 T28N		I	11. County or Parish, State San Juan County, NM		
12. CHEC	K THE APPROPRIATE BOX(I	ES) TO INDICATE NATUR	È OF NOTIC	E, REPORT OR OTHE	ER DATA
TYPE OF SUBMISSION		TYPE OF ACTION			
Notice of Intent  Subsequent Report	☐ Acidize ☐ Alter Casing ☐ Casing Repair	Deepen Fracture Treat New Construction	Reclar	ction (Start/Resume) mation nplete	Water Shut-Off Well Integrity Other
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back		orarily Abandon Disposal	
Attach the Bond under which the was following completion of the involve testing has been completed. Final determined that the site is ready for McElvain Energy, Inc. proposes to my Work will commence once partner as	ed operations. If the operation r Abandonment Notices must be fi r final inspection.) epair the casing leak as per the	esults in a multiple completi iled only after all requiremen	on or recompl nts, including r	etion in a new interval,	a Form 3160-4 must be filed once
					RCVD MAY 10 '13 OIL CONS. DIV.
		Notify NMOCD prior to begin operation	ining		DIST. 3
• .					
I hereby certify that the foregoing is to Deborah Powell	ue and correct. Name (Printed/Ty	Title Eng Te	ch Manager		
Signature Delle K	Mul	Date 05/07/2	2013		
1	THIS SPACE FO	OR FEDERAL OR S	TATE OFF	ICE USE	
Approved by Original	Signed: Stephen Mason	Title			MAY 0 8 2013
Conditions of approval, if any, are attached that the applicant holds legal or equitable t	I. Approval of this notice does not itle to those rights in the subject le	t warrant or certify		,-	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

entitle the applicant to conduct operations thereon.

### McElvain Energy, Inc.

## Federal Com 2R April, 2013 Repair Procedure

LOCATION: Sec. 12 T28N R13W

**API:** 30-045-23512

1085 FSL, 285 FWL San Juan, County, NM

**TD:** 6154'

**PBTD:** RBP @ 4887 original 5543 **RKB:** 6785 **GL:** 6773

#### PURPOSE OF WORK:

Repair casing leak, fish and recover tubing anchor and return well to production as a Gallup Mancos producer.

#### **CASING:**

8 5/8", 24#, K-55, STC @ 163' . Cemented with 100 sx class B w/ 3% CC. Cement circulated.

4-1/2", 10.5#, J-55 at 6153' with DV tool at 4217 and 1589 in 7-7/8" hole Cemented with a total of 910 sx cement.

#### **FORMATION TOPS:**

Pictured Cliffs	1398
Cliff House	2340
Mancos	4163
Gallup	5083
Greenhorn	5879
Dakota	5984

#### PERFORATIONS:

5988, 90, 91, 93, 94, 96, 97, 6012, 14, 15, 17, 18, 76, 78, 79, 81, 82, 84. Possible sand bridge at 604 and solid fill at 6070 Retrievable Bridge Plug at 5967.

#### FRAC:

TUBING: 2-3/8", 4.7# tubing set at 5893 with retrieving head.

#### CASING LEAK:

2379 to 2221 has been confirmed. Could not get a packer seat between 2379 and 2221. Pressure up to 500 psi and bleeds off to 250 in 30

McElvain Energy, Inc. Fed Com #2R April, 2013 Casing Repair Page #2

#### PROCEDURE:

- 1. MI & RU workover rig.
- 2. Rig up service unit and BOP.
- 3. Tag bridge plug at 5967 and retrieve.
- 4. Pull tubing and plug.
- 5. Rig up wire line and run caliper tool to verify casing weights and grade. as per Blue Jet recommendation attached. Order casing patch.
- 6. Run bit and scrapper on tubing and reverse circulate fill from 6040 to PBTD. Pull tubing.
- 7. Pick up casing patch and run in the hole. Deploy casing patch with top of patch at 2215 and bottom of patch at 2385. Run MIT
- 8. Pull tubing and lay down setting tools.
- 9. Run 2 3/8 tubing with notch collar and seating nipple and land tubing at +/- 6075.
- 10. Swab well in. Drop bumper spring and plunger and return well to production.

NOTE:
DO NOT USE LIQUID KCl SUBSTITUTE in COMPLETION FLUIDS