

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: San Juan 31-6 Unit 213	Facility Type: Gas Well

Surface Owner Federal	Mineral Owner Federal (NM-03404)	API No. 30-039-24531
------------------------------	---	-----------------------------

LOCATION OF RELEASE

Unit Letter K	Section 5	Township 30N	Range 6W	Feet from the 1865	North/South Line South	Feet from the 1595	East/West Line West	County Rio Arriba
-------------------------	---------------------	------------------------	--------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude 36.83943 Longitude 107.48935

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 113 bbls	Volume Recovered 112 bbls
Source of Release PRV at transfer pump	Date and Hour of Occurrence Unknown	Date and Hour of Discovery March 4, 2013 at 1:22pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM (Mark Kelly) and NMOCD (Brandon Powell)	
By Whom? Crystal Tafoya	Date and Hour 3/5/2013 at 3:27pm & 3:29pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

**RCVD MAR 11 '13
OIL CONS. DIV.
DIST. 3**



Describe Cause of Problem and Remedial Action Taken.*

Pressure relief valve at the transfer pump froze and pulled out of the threaded connection causing 113 bbls of produced water to be released. The well was shut-in and water trucks called to location. 112bbls was recovered and contained within the berm.

Describe Area Affected and Cleanup Action Taken.*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 6/6/2013	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/6/2013 Phone: (505) 326-9837		

* Attach Additional Sheets If Necessary

NJK1315752269