

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report



Name of Company Burlington Resources Oil & Gas Company	Contact Crystal Tafoya	
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837	
Facility Name: McCord 12E	Facility Type: Gas Well	
Surface Owner Fee	Mineral Owner BLM (SF-078214)	API No. 30-045-26301

LOCATION OF RELEASE

Unit Letter O	Section 33	Township 30N	Range 13W	Feet from the 1093	North/South Line South	Feet from the 1748	East/West Line East	County San Juan
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

Latitude 36.76574 Longitude 108.20739

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 6 bbls	Volume Recovered 1 bbl
Source of Release Produced Water Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 5/23/13 at 7:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Produced water tank vessel seam discovered to be leaking. Approximately 6bbls of produced water was released and 1bbl recovered.		
Describe Area Affected and Cleanup Action Taken.* ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 		OIL CONSERVATION DIVISION
Printed Name: Crystal Tafoya		Approved by Environmental Specialist: 
Title: Field Environmental Specialist		Approval Date: 6/12/2013 Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com		Conditions of Approval:
Date: 5/29/2013 Phone: (505) 326-9837		Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

NSK1316342289