

June 4 , 2013

RCVD JUN 14 '13

OIL CONS. DIV.

DIST. 3

Koch Exploration Co LLC  
950 17<sup>th</sup> Street Suite 1900  
Denver , CO 80202

This letter is to certify that D & D Services LLC did run deviation surveys at the below listed depths on your Bisti 36 # 1 in San Juan County , New Mexico .

Bisti 36 # 1                      S 36 T 25N R 1~~8~~<sup>3</sup> W      API # 30-045-35385


125                                       $\frac{3}{4}$

625                                      1  $\frac{1}{4}$

1125                                    1  $\frac{3}{4}$

To the best of my knowledge, I swear this information to be true.

Sincerely,



Glen Davis  
Drilling Manager

