



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distic.htm](http://emnrd.state.nm.us/ocd/District%20III/3distic.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-18-2013 Operator CoPC API #30-0 39-07149

Property Name San Juan 28-6 Well No. 43 Location: Unit A Section 7 Township 27 Range 2

Well Status(~~Shut In~~ or Producing) Initial PSI: Tubing 111 Intermediate 3.5 Casing 114 Bradenhead 0.2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead		Int	Csg
TIME		Int	Csg		
5 min	0	3.5	114	0	115
10 min	0	3.5	115	0	115
15 min	0	3.5	115	0	115
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Just a whisper from bradenhead. Intermediate blew
down in 18 seconds

By [Signature]
(Position) MSD

Witness Paul Wihre

E-mail address _____