



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD JUN 27 '13  
OIL CONS. DIV.

DIST. 3

Date of Test 27-JUNE-2013 Operator CONOCO API #30-0 39-07382

Property Name SAJUAN 28-7 UNIT Well No. 49 Location: Unit B Section 21 Township 28 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 95 Intermediate 112 Casing 96 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	1	1.26	97		98
10 min		5	98		99
15 min		6	98		10
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	X
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1.8

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT.  
OPENED THE INTERMEDIATE AND IT BLEW DOWN WITHIN  
IN LESS THAN 1 SECOND

By Ana Cordova

Witness John Duerksen

Area 23 mgr

(Position)

E-mail address \_\_\_\_\_