



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emrmd.state.nm.us/ocd/District/III3distr.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

JUL 16 2013

Date of Test 7-16-2013 Operator COPC API #30-0 39-20356

Property Name San Juan 29-5 Well No. 53 Location: Unit L Section 32 Township 29 Range 5

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 126 Intermediate 0 Casing 137 Bradenhead -0.6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	0	137	0	137
10 min	0	0	137	0	137
15 min	0	0	137	0	137
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR  FRESH  SALTY  SULFUR  BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: Just a puff on bradenhead Intermediate slight blow, down to nothing in 6 seconds.

By [Signature]

Witness Paul [Signature]

(Position)

E-mail address \_\_\_\_\_