



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emnrd.state.nm.us/ocd/District III/3district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAY 01 2013

Date of Test 4-19-13 Operator WPX Energy API #30-0 3924425

Property Name Rosa Unit Well No. 223 Location: Unit A Section 30 Township 31N Range 05W

Well Status(Shut-In or Producing) Initial PSI: Tubing 60 Intermediate N/A Casing 61 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

Braden head valve left open after test

By Stanley Dean

Witness \_\_\_\_\_

S.C. Tech  
(Position)

E-mail address \_\_\_\_\_