

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

ſ	BRADENHEAD TEST REPORT (submit 1 copy to above address)	RCVD AUG 1 '13 OIL CONS. DIV. DIST. 3
Date of Test	Operator BTAMerica A	PI#30-0 <u>45-11653</u>
Property Name F Mulle Well No. 514 Location: Unit Section Workship 30 Range 9		
Well Status(Shut-In or Producing) Initial PSI: Tubing <u>15</u> Intermediate <u>14</u> Casing Bradenhead <u>12</u>		
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH		
PRESSURE Testing Bradenhead BH Int Csg/Filler Int		CHARACTERISTICS AD INTERMEDIATE
TIME / 75	Steady Flow	
10 min 1 75	Surges	
15 min / 75	Down to Nothing	
20 min 1 74	Nothing	
25.min	Gas	
30 min §	Gas & Water	
• •	Water	
If bradenhead flowed water, check all of the descriptions that apply below:		
CLEAR FRESH SALTY SULFURBLACK		
5 MINUTE SHUT-IN PRESSURE BRADENHEAD 85 INTERMEDIATE		
REMARKS: + and blow fust 15 seconds then Medlight		
Notubing Dimiliple- Sassimple taken		
Cusing Sumeas BHON Sthen Shuta		
By Ray Jodesma Witness 910 Millia Cuelling		
(Position)		
E-mail address		
	· · ·	