

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Lisa Hunter
Address	3401 East 30 th Street, Farmington, NM 87401	Telephone No.	505-326-9786
Facility Name	Lackey B LS #13	Facility Type	Gas Well

Surface Owner	Federal	Mineral Owner	Federal	API No.	3004507289
---------------	---------	---------------	---------	---------	------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	20	28N	9W	1650	South	1650	North	San Juan

Latitude 36.644699 Longitude -107.81491

NATURE OF RELEASE

Type of Release	Conventional - Produced Water	Volume of Release	5 BBLs	Volume Recovered	5 BBLs
Source of Release	Pit Tank	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	06/13/13 @ 11:30 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	N/A		
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*
N/A

RCVD JUN 25 '13
OIL CONS. DIV.
DIST. 3



Describe Cause of Problem and Remedial Action Taken.*

5 BBLs of produced water leaked from water pit tank due to corrosion. Water hauler pulled produced water from lined pit and all liquids (5 BBLs) were recovered. Pit tank will be replaced.

Describe Area Affected and Cleanup Action Taken.*

All fluids were captured in liner. Water hauler pulled produced water from lined pit and all liquids were recovered. No further remediation is required at this time.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lisa M. Hunter	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 8/1/2013	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 21, 2013 Phone: 505-326-9786		

* Attach Additional Sheets If Necessary

NSR1321336280