

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

RCVD AUG 7 '13

	HEAD TEST REPORT  copy to above address)  OIL CONS. DIV.
Date of Test 8.7-13 Operator Basin I sposulAPI #30-0 45-26862  Property Name Disposul Well No. 1 Location: Unit F Section Township 39 Range //	
Well Status(Shut-In or Producing) initial PSI: Tubing 190 Intermediate Casing 190 Bradenhead	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min O O	Steady Flow
10 min 0 0	Surges
15 min 0 0	Down to Nothing
20 min	Nothing
25 min	Gas
30 min	Gas & Water
Water	
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY	SULFURBLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE	
REMARKS: Nothing When opened.	
O: $I$	
By Paul II Witness Monda Cuchling	
(Position)	
E-mail address	