

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT JUL 18 2013FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

5. Lease Serial No.
142060462
6. If Indian, Allottee or Tribe Name
UTE MOUNTAIN UTE
7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
UTE DOME 3A

9. API Well No.
30-045-11165-00-S1

10. Field and Pool, or Exploratory
UTE DOME

11. County or Parish, and State
SAN JUAN COUNTY, NM

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
XTO ENERGY

Contact: SHERRY J MORROW
E-Mail: sherry_morrow@xtoenergy.com

3a. Address
382 CR 3100
AZTEC, NM 87410

3b. Phone No. (include area code)
Ph: 505-333-3630

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Sec 35 T32N R14W SENE Tract H 1650FNL 990FEL

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

XTO Energy Inc. has plugged and abandoned this well per the following:

Notified COBLM & NMOCD 7/10/2013 @ 1:30 p.m. of P&A ops.

7/11/2013 MIRU.


7/12/2013 TOH 2-3/8", 4.7# J-55, 8rd, EUE tbg. TIH CIRC. Set CIRC @ 2,330'. PT tbg to 800 psig. Tstd OK. Plg #1 w/16 sx Type B cmt (mixed @ 15.6 ppg, 1.18 cu ft/sx). Cmt plg fr/2,330' - 2,120'. Plg #2 w/16 sx Type B cmt (mixed @ 15.6 ppg, 1.18 cu ft/sx). Cmt plg fr/1,726' - 1,516'. MIRU WLU. Perf sqz holes @ 578'. WO orders fr/COBLM. Alan White & Marie Lope w/COBLM on loc.

7/15/2013 Dan Rabinowitz w/COBLM requested PT csg to 1,100 psig & perf sqz holes @ 528' @ 6:15 p.m.

**SEE ATTACHED
CONDITIONS OF APPROVAL****RCVD AUG 9 '13
OIL CONS. DIV.
DIST. 3**

14. I hereby certify that the foregoing is true and correct.	
Electronic Submission #214089 verified by the BLM Well Information System For XTO ENERGY, sent to the Durango Committed to AFMSS for processing by BARBARA TELECKY on 07/19/2013 (13BDT0111S)	
Name (Printed/Typed) SHERRY J MORROW	Title REGULATORY ANALYST
Signature (Electronic Submission)	Date 07/18/2013

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By 	Title M. S. C.	Date 8/1/13
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office TRES RIOS FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **** A

Additional data for EC transaction #214089 that would not fit on the form

32. Additional remarks, continued

7/14/2013. Rec verbal approval fr/Charlie Perrin w/NMOCD to perf @ 528' @ 7:45 a.m. 7/15/2013. PT 4-1/2" csg fr/1,516' (TOC) - surf to 2,000 psig. Tstd OK. RU WLU. Perf sqz holes @ 528'. RD WLU. TIH CICR. Set CICR @ 493'. PT tbg to 1,500 psig. Tstd OK. Plg #3 w/109 sx Type B cmt (mixed @ 15.6 ppg, 1.18 cu ft/sx). 97 sx cmt below CICR & 12 sx cmt abv CICR. Cmt plg fr/493' - 335'. MIRU WLU. Perf sqz holes @ 100' FS. RDMO WLU. Plg #4 w/77 sx Type B cmt (mixed @ 15.6 ppg, 1.18 cu ft/sx). Circ gd cmt to surf. Marie Lope w/COBLM on loc.

7/16/2013 Cut off WH. Found TOC in 4-1/2" x 7" csg @ surf. Set DH marker w/24 sx Type B cmt (mixed @ 15.6 ppg, 1.18 cu ft/sx). RDMO. Marie Lope w/COBLM on loc.

XTO Energy
Tribal Lease: 14-20-604-62
Well: Ute Dome #3 A
1650' FNL & 990 FEL
Sec. 35, T. 32 N., R. 14 W.
San Juan County, New Mexico

3160

Conditions of Approval - Subsequent Report of Abandonment:

This approval is for the completion of the downhole plugging portion of the well only. Surface reclamation must be completed, weed free vegetation established, and site accepted by the BIA prior to closure and bond release.

The Bureau of Land Management, SJPLC ([Ryan Joyner@co.blm.gov](mailto:Ryan.Joyner@co.blm.gov) or 970.385.1242) shall be notified at least 48 hours prior to commencement of surface reclamation. The BIA-UMU (970.565-6094) and UMU Tribal Energy at 970.564-5690 shall be contacted prior to surface reclamation procedures for specific requirements and seed mixtures.

In general:

- Well equipment (meterhouses and associated pipelines, dehydrators, separators, Pump jacks, pump jack supports, wellheads, tanks and supports, dead-men and anchors, concrete slabs and, cables, piping) fences, guards and all trash shall be removed, slash piles chipped and scattered. Pipelines shallower than 30" deep shall be removed to the tie-in. Deeper lines may be purged and capped. A surface mounted P&A marker shall be erected per Onshore Order #2 with API Number, Name of operator, Name of well and number, lease serial number and surveyed location as 43CFR 3162.6(B)

- *All earthen pits and boreholes shall be filled, the access road restored, berms knocked down, well pad and access road surface re-contoured as close to original landscape as possible to blend with surrounding terrain and recreate original drainages, stabilize soil, spread top soil evenly redistributed.*

- *The site shall require weed control, soil preparation and analysis for the application of amendments as required to foster plant growth and reseeding with a BIA approved seed mix at the specified rate. The soil shall be drill seeded when possible with a BIA approved weed free seed mix tailored to the site. Straw mulch or an effective tackifier shall be applied to retain the seed and provide moisture retention. The site shall be monitored for self-sustaining growth. Unless 70% restoration of vegetation is accomplished, reseeding will be required prior to release of bond liability.*

- *When the site is revegetated the operator shall send a "Final Abandonment Notice" to the BLM to initiate an analysis of restoration success by the BLM and BIA. If further remediation is required the operator will be notified.*

According to the regulations in 43 CFR 3162.3-4, a well site is to be reclaimed and re-vegetated directly following plugging. Onshore Order #1 and BLM-SJRA stipulate that surface reclamation be completed within 180 days of final plugging operation completion but may be commenced directly after the plugging operation while equipment is available. When re-vegetation has subsequently been re-established, BLM shall be notified by the operator with a Final Abandonment Notice. A field inspection will then be arranged between the SUIT/UMU Tribe, the BLM and the respective BIA agency, so that the well pad can be inspected for release from bond liability

- Please submit a final wellbore diagram upon receipt of these COAs.
- After the FAN is approved by this office, your liability associated with the subject well will terminate.