

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

RCVD AUG 19'13 OIL CONS. DIV.

BRADENHEAD TEST REPORT

DIST. 3

| (submit 1 copy to above address) | |
|---|---|
| Date of Test 8-19-13 Operator Bulung Touces API #30-0 45-28563 | |
| Property Name 532-965 Well No. 5 Location: Unit A Section 18 Township 31 Range 9 | |
| Well Status (Shut-In or Producing) Initial PSI: Tubing 46 Intermediate // Casing 4 Bradenhead O | |
| OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH | |
| PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg | FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE |
| TIME 0 -6 | Steady Flow |
| 10 min 0 -6 | Surges |
| 15 min 0 - 0 | Down to Nothing |
| 20 min | Nothing |
| 25 min | Gas |
| 30 min_ | Gas & Water |
| - Water | |
| If bradenhead flowed water, check all of the descriptions that apply below: | |
| CLEAR FRESH SALTY | SULFURBLACK |
| 5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE /// | |
| REMARKS: Lightbow when of Dened. lighter at Menute | |
| duct it 3 minutes | |
| | |
| By Witness / Oula Cullung | |
| Scap M 50 (Position) | |
| - " " | |