Submit 3 Copies To Appropriate DistrictState of New MexicoOfficeEnergy, Minerals and Natural Resources	Form C-103 Jun 19, 2008		
1625 N. French Dr., Hobbs, NM 88240District II1301 W. Grand Ave., Artesia, NM 88210OIL CONSERVATION DIVISION	WELL API NO. 30-039-24317		
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE SFEE		
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. E-347-20		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name San Juan 30-6 Unit		
PROPOSALS.) 8. Well Number 443 1. Type of Well: Oil Well Gas Well Other 8. Well Number 443			
2. Name of Operator 9. OGRID Number			
Burlington Resources Oil Gas Company LP 3. Address of Operator	s Company LP 14538 10. Pool name or Wildcat		
P.O. Box 4289, Farmington, NM 87499-4289	Basin Fruitland Coal		
4. Well Location Unit Letter <u>G</u> : 2200 feet from the <u>North</u> line and <u>1360</u> feet from the <u>East</u> line			
Section 36 Township 30N Range 6W	NMPM Rio Arriba County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6807' GR			
12. Check Appropriate Box to Indicate Nature of Notic	ce, Report or Other Data		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W TEMPORARILY ABANDON COMMENCE COMMENCE	COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JOB RCVD JUL 15 '13 DIL CONS. DIV.		
	DIST. 3		
OTHER: 🗌 🛛 🖸 Location	is ready for OCD inspection after P&A		
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It show the 			
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKERS SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.			
 Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. 			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)			
 Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines. 			
When all work has been completed, return this form to the appropriate District office to	schedule an inspection.		
SIGNATURE			
For State Use Only	phillips.com PHONE: 505-324-6104		
APPROVED BY: The Letter TITLE Dist	a Gas Inspector, rict #3DATE 2 7 AU-20 3		

Conditions of	Approval	(if any
---------------	----------	---------