Submit @ Copies To Appropriate District Office	State of N Energy, Minerals a			s				rm C-103 Jun 19, 2008
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Ellergy, Willerais a	na rata	ai resources	۲ آ	WELL AP			
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVA	ATION	DIVISION				45-21702	
District III	1220 South S				5. Indicate	Type of		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe,	NM 87	505	te			Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505							2-5384	
		EN OR PLU			<u> </u>	State C		ent Name
· · · · ·	Gas Well 🛛 Other			8	3. Well Ni	umber 7	Α	
2. Name of Operator				9	. OGRID			
ConocoPhillips Company					0 Dec1 -		<u>17817</u>	
3. Address of Operator P.O. Box 4289, Farmington, NM 87	499-4289				10. Pool name or Wildcat Blanco Mesaverde			
4. Well Location				000	6 / 6	.1	F (1.
Unit Letter P : 990 Section 32				<u>990</u>	feet fro ↓MPM		East	_line
Section 32	Township 31N 11. Elevation (Show whe		nge 8W			San Ju	an County	
	11. Elevation (Show whe	6315'		, <i>erc.)</i>				
12. Check Ag	propriate Box to Ind	icate Na	ature of Not	tice, R	eport or	Other D	Data	
NOTICE OF INT		J	c				ORT OF:	
		п	REMEDIAL				ALTERING C	asing 🖂
	CHANGE PLANS		COMMENCE		ING OPNS		P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEI	MENT J	OB			
DOWNHOLE COMMINGLE								
OTHER:		X	OTHER:	1				
13. Describe proposed or comple	ted operations. (Clearly s			ls, and g	ive pertine	ent dates.	, including e	stimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.								
Purlington Descurace intends to nor	form on MIT tost on su	bioot wol	l as nor tha N	MOCI) rogulati	one roau	iring MIT (NORY
Burlington Resources intends to perform an MIT test on subject well as per the NMOCD regulations requiring MIT every 5 years. The last MIT was performed 10/3/2008. This MIT is also to extend TA status. Procedure is attached.								
							D AUG 28 '	19
		Notify N	MOCD 24 hrs	e			CONS. DI	
	Ĺ	prior (to beginning	3			DIST. 3	
	h	ор	erations				VI.0	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.								
SIGNATURE	T T	ITLE	Regulatory	Technie	cian DA	ATE	8/27/13	
Type or print name Kenny Davis	E-mail address:	Ken	ny.r.davis@cc	onocoph	illips.com	PHO	NE: 505-59	9-4045
For State Use Only	7 .		•					
APPROVED BY:	И т	ITLE	eputy Oil	& Gas			DATE 8- 2	28-13
Conditions of Approval (if any):	\mathcal{L}			SUICE	<u> </u>		DATE <u>010</u>	
· · · · · · · · · · · · · · · · · · ·	-	A/						

,

3/6

ConocoPhillips STATE COM K 7A Expense - MIT

		Lat 36° 51' 0.184" N	8	Long 107° 41' 31.	92'' W			
Prepared by: Supervisor:	Brett Grema Jim Fodor	ux				Date:	August 14	i, 2013
Twinned Location:	No		Currently S	Surface Comming	led:	No		
Scope of Work:	Perform MIT	on TA'd well.						
Est. Rigless Days:	1	Formation:	MV	Area:	5		Route:	508
WELL DATA API: LOCATION:	3004521702 990' FSL & S	990' FEL, Spot P, Sectio	on 32 -T 0311	Spud Date N - R 008W	: 6/15/1975	i		
Artificial lift on well	<u>(type):</u>	None	Estimated	Shut in Casing Pr	essure:	()	
<u>H2S:</u>	0 ppm ALV	WAYS VERIFY		<u>Well Clas</u>			II Category	

Special Requirements:

Pump truck, chart recorder, contact the NMOCD 10 days prior to conducting MIT.

Contacts	Name	Office #	Cell #
Well Intervention Engineer	Brett Gremaux	326-9588	215-7086
WI Backup Engineer	Jessie Dutko	599-3422	320-0765
PE Production Engineer	Erica Herring	326-9854	608-4631
MSO	Michael Cordova		787-6083
Lead	Steve Baird	599-3457	320-2511
Area Foreman	Jim Peace	324-5173	320-0210

Well History/Justification

The State Com K #7A was drilled and completed as a Mesa Verde stand alone in 1975. It was completed with 2 frac's in the Point Lookout and Cliffhouse. In 1996, a 3000 psi flanged wellhead was installed prior to a payadd to the Menefee and Lewis. The well was TA'd in 2008 due to a Mesa Verde recomplete to the State Com AL 36 that resulted in the wells being on 40 acre density. During the TA, the tubing was pulled, a CIBP was set at 3918', the hole was loaded with 2% KCl, and the casing was tested to 1000 psi.

Recommendation

The well has been in TA status for 5 years and requires a mechanical integrity test. Required by 10/13/13.

Lo le Superintendent Wells-Engineer Date: 8-15-Date: 8-19-

Engineering Supervisor 8 Date:

1

ConocoPhillips STATE COM K 7A Expense - MIT

Lat 36° 51' 0.184" N

Long 107° 41' 31.92" W

PROCEDURE

Ensure NMOCD has been contacted 10 in advance of MIT

1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations.

2. Check casing and bradenhead pressures and record them in Wellview. If there is pressure on the BH, contact Production Engineer to review complete BH history and have a gas analysis done.

3. Move in water truck. Load hole with 2% KCI. Move off water truck.

4. Move in pump truck and connect hose to 7" casing valve. Load w/ 2% KCI if necessary.

5. Pressure up on 7" casing to 600 psi. Hold stabilized pressure for a minimum of 30 minutes and record on a 2 hour chart with a 1000# spring. If test passes, shut well in. Rig down pump truck and move off location. Provide chart to Wells Engineer. If test fails, contact Rig Superintendent and Wells Engineer.

Schematic - Current ConocoPhillips STATE COM K #7A							
District NORTH	·	Field Name MV	API / UWI 300452170	County 2 SAN JUAN	State/Province Edit NEW MEXICO		
Original	Spud Date	Surface Legal Location	East/West Distance (ft)	East/West Reference North/South	Distance (ft) North/South Reference		
	<u>5/1975</u>	NMPM-31N-08VV-32-P	990.00	E 99	0.00 S		
		<u> </u>	Vell Config: Vertical - Or	Iginal Hole, 8/14/2013 2:10:56 PM			
fike	ftKÐ			· · · · · · · · · · · · · · · · · · ·	\$ }		
_(MD)	(TVD)		Schematic - Acti		Frin Final		
13		himmer and the second		Des:Original Hole, OD:13, Depth	•		
149	: ·			(MD):13-150			
150		10 3/4in, 13 ftKB, 150		Surface Casing cement, 13-150, 3/22/1975			
1,995		ftKB, 32.75ibs/ft		Des:Original Hole, OD:6 3/4, Depth	Ojo Alamo, 1,995		
				(MD):150-3,422			
2,064					Kirtland, 2,064 ———		
2,887		······································			Fruitland, 2,887		
3,160		· · · · · · · · · · · · · · · · · · ·	-8 8		Pictured Cliffs, 3,160		
3,221							
3,227							
3,421		a a secondaria de la composición de la		· · · ·			
3,422		7in, 13 ftKB, 3,422 ftKB,		Intermediate casing cement,			
3,918		23.00lbs/ft		1,250-3,422, 6/22/1975			
		Bridge Plug - Temporary, 3,918-3,923					
3,923		· · · · · · · · · · · · · · · · · · ·					
3,968		Fracture, 3,968-4,309,		• • • • •			
4,309		11/12/1996		Des:Original Hole, OD:6 1/4, Depth (MD):3,422-5,705	· ·		
4,990				[[wiii]]:3;422-3;703	Cliff House, 4,990		
4,992		Fracture, 4,992-5,048,					
5,048		7/10/1975					
5,052					Menefee, 5,052		
5,123							
5,239		Fracture, 5,123-5,239, 11/7/1996					
			BB				
5,323		,,	14 14	a and the second se			
5,365				. <u>1. ann a fha an an tar an an an tar an an tar an </u>	Point Lookout, 5,365		
5,380		Fracture, 5,380-5,525					
5,525		7/9/1975		·	• ·		
5,533		<u> </u>		<u></u>	Mancos, 5,533		
5,555	- I	· .		CEMENT PLUG, 5,645-5,705,			
5,704		PBTD @ 5645'	E Constant	6/28/1975 TD, 5,705 ftKB, 6/27/1975			
5,705	ļ	4 1/2in, 3,221 ftKB, 5,705		Production Liner Cement,	,		
		ftKB, 10.50lbs/ft		3,221-5,705,6/27/1975	·		
1.4.8.	1		·蒙·德·德·哈·克	Page 1/1	Report Printed: 8/14/2013		

,