

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company WPX Energy	Contact Buddy Shaw	
Address P. O. Box 640 Aztec, NM 87410	Telephone No. 505-386-8097	
Facility Name Rosa Unit 259	Facility Type Gas Well	
Surface Owner Federal	Mineral Owner Federal	API No. 30-039-24612

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	33	31N	5W					Rio Arriba

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 25 bbls	Volume Recovered 20
Source of Release Compressor	Date and Hour of Occurrence	Date and Hour of Discovery 7/31/2013 9AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	RCUD AUG 29 '13
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. OIL CONS. DIV. DIST. 3	

If a Watercourse was Impacted, Describe Fully.\*

NA

Describe Cause of Problem and Remedial Action Taken.\*

Transfer pump failure-leaked water to ground.

Describe Area Affected and Cleanup Action Taken.\*

NA - No remediation required. Chloride level was 220ppm

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Buddy Shaw		Approved by Environmental Specialist: Jonathan D. Kelly	
Title: Environmental Supervisor		Approval Date: 9/11/2013	Expiration Date:
E-mail Address: buddy.shaw@wpenergy.com		Conditions of Approval:	
Date: 8/1/2013	Phone: 386-8097	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

nJK 1325440095



## Analytical Report

### Report Summary

Client: WPX Energy, Inc.

Chain Of Custody Number: 12771

Samples Received: 8/2/2013 9:00:00AM

Job Number: 04108-0137

Work Order: P308009

Project Name/Location: Rosa Unit 259 Spill

Entire Report Reviewed By:

A handwritten signature in black ink, appearing to read 'Tim Cain', is written over a horizontal line.

Date: 8/13/13

Tim Cain, Laboratory Manager

The results in this report apply to the samples submitted to Envirotech's Analytical Laboratory and were analyzed in accordance with the chain of custody document supplied by you, the client, and as such are for your exclusive use only. The results in this report are based on the sample as received unless otherwise noted. Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc. If you have any questions regarding this analytical report, please don't hesitate to contact Envirotech's Laboratory Staff.



WPX Energy, Inc.  
PO Box 21218  
Tulsa OK, 74121-1358

Project Name: Rosa Unit 259 Spill  
Project Number: 04108-0137  
Project Manager: Vanessa Fields

**Reported:**  
13-Aug-13 09:04

### Analytical Report for Samples

Client Sample ID	Lab Sample ID	Matrix	Sampled	Received	Container
Rosa 259 Spill	P308009-01A	Soil	08/01/13	08/02/13	Glass Jar, 4 oz.

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

5796 US Highway 64, Farmington, NM 87401

Three Springs - 65 Mercado Street, Suite 115, Durango, CO 81301

Ph (505) 632-0615 Fx (505) 632-1865

Ph (970) 259-0615 Fr (800) 362-1879

envirotech-inc.com

laboratory@envirotech-inc.com



WPX Energy, Inc.	Project Name:	Rosa Unit 259 Spill	
PO Box 21218	Project Number:	04108-0137	Reported:
Tulsa OK, 74121-1358	Project Manager:	Vanessa Fields	13-Aug-13 09:04

**Rosa 259 Spill**  
**P308009-01 (Solid)**

Analyte	Result	Reporting		Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		Limit								
Cation/Anion Analysis										
Chloride	220	9.99	mg/kg	1	1331033	02-Aug-13	02-Aug-13	EPA 300.0		

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.