District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

## State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1220 S. St. Francis Dr., Santa Fe, NM 87505 Release Notification and Corrective Action **OPERATOR Initial Report** Final Report Name of Company WPX Energy Contact **Buddy Shaw** Address P. O. Box 640 Aztec, NM 87410 Telephone No. 505-386-8097 Facility Name Chaco 2307-12E #168H Facility Type Oil Well Surface Owner Federal Mineral Owner Federal API No. 30-039-31173 LOCATION OF RELEASE North/South Line Feet from the Unit Letter Section Township Range Feet from the East/West Line County E 12 7W 23N Rio Arriba Latitude Longitude NATURE OF RELEASE Type of Release Fire-Oil to Flare Volume of Release 10 gals Volume Recovered Source of Release Wellhead Date and Hour of Occurrence Date and Hour of Discovery 9/6/2013 5AM Was Immediate Notice Given? If YES, To Whom? ☐ Yes ☒ No ☐ Not Required Date and Hour
If YES, Volume Impacting the Waterpyrse.

CONS. DIV DIST. 3 By Whom? Was a Watercourse Reached? ☐ Yes ⊠ No If a Watercourse was Impacted, Describe Fully.\* SEP 0 9 2013 NA Describe Cause of Problem and Remedial Action Taken.\* Low pressure caused oil dumps to remain open causing a small amount of oil to reach the flare causing fire droppings to ground surface and catching a small propane tank on fire. Fire put out with water tank setting near by. Knockout separators will be installed on all flare locations. Stain soil was removed and placed in cuttings pit. Describe Area Affected and Cleanup Action Taken.\* NA I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISIO Signature: Approved by Environmental Specialist: ( Printed Name: **Buddy Shaw** Approval Date: Of Title: **Environmental Supervisor** E-mail Address: buddy.shaw@wpxenergy.com Conditions of Approval: Attached

Phone:386-8097

9/6/2013

MX1325436597

<sup>\*</sup> Attach Additional Sheets If Necessary