

## NEW MEXICO ENERGY, MUNERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(500) 324 6178 EAV. (500) 324 6170

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

OIL CONS. DIV DIST. 3

## **BRADENHEAD TEST REPORT**

JUN 05 2013

(submit 1 copy to above address)

Date of	f Test <u>s</u>	5-23-1	3_Op	erator <u>E</u>	lm Ridge	Expl	oration CO LL	<u>.C</u> _API #30-0	39-21738	
Property Name <u>Candado</u> Well No. <u>022 A</u> Location: Unit <u>D</u> Section <u>4</u> Township <u>26N</u> Range <u>07W</u>										
Well Status(Shut-In or Producing) Initial PSI: Tubing II6 Intermediate Casing 121 Bradenhead										
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH										
_	PRESSURE Testing Bradenhead INTERN BH Int Csg Int						FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE			
TIME 5 min_	0		121			-	Steady Flow			
10 min_	0		121				Surges			
15 min_	0		121				Down to Nothin	g		
20 min_	0		121				Nothing			
25 min_	0		121				Gas			<del></del>
30 min_	0		121				Gas & Water	· · · · · · · · · · · · · · · · · · ·		
							Water			
If bradenhead flowed water, check all of the descriptions that apply below:										
CLEAR FRESH					SALTYBLACK_			_BLACK		
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE REMARKS:										
									·	
By Jason Herbic					Witness					
PUMPER (Position)										
E-mail address										