



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

AUG 20 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-8-13 Operator Devon API #30-0 3907930
3907390

Property Name NEBU Well No. 28 Location: Unit ___ Section ___ Township ___ Range ___

Well Status(Shut-In or Producing) Initial PSI: Tubing 65 Intermediate - Casing 73 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>N/A</u>	<u>73</u>		
10 min	<u>0</u>		<u>73</u>		
15 min	<u>0</u>		<u>73</u>		
20 min	<u>0</u>		<u>73</u>		
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>✓</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ___ FRESH ___ SALTY ___ SULFUR ___ BLACK ___

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

By DAN MCELLOGAN
LEASE OPERATOR
(Position)

Witness Anthony Pacheco

E-mail address _____

