

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT



BRADENHEAD TEST REPORT OIL CONS. DIV DIST. 3

(submit 1 copy to above address)

AUG 1 3 2013

Date of Test 6 18 30-043-07022 Operator Elm Ridge Exploration CO LLC API #30-043-07022

Property Name: Jicarilla 55_Well No. 002_Location: Unit M_Section 35_Township 23N_Range 03W_

Well Status(Shut-In or Producing) Initial PSI: Tubing 45 Intermediate Casing 45 Bradenhead

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE						FLOW CHARACTERISTICS	
Testing		Braden	head	INTEI	RM	BRADENHEAD INTERMEDIATE	
r	BH	Int	Csg	Int	Csg		
TIME 5 min	D	45	6.5			Steady Flow	
10 min_	0	65	65			Surges	
15 min	P	45	45			Down to Nothing	
20 min_			-			Nothing	
25 min_						Gas	
30 min_						Gas & Water	
						Water	
If bradenhead flowed water, check all of the descriptions that apply below:							
CLEAR FRESH				S	SALTY	SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD D						EAD INTERMEDIATE	
REMARKS:							
	<i>j</i>					· · · · ·	
By <u>fiel Duan</u> Witness							
<u>Position</u> witness							
	()					
E-mail address							